

REPLACEMENT PARTS

PRICE LIST

UNITED STATES

EFFECTIVE MARCH 01, 2009

TERMS AND CONDITIONS

Placing Orders

All orders should include customer number, buyer name and contact information and price quotation number, if applicable. Orders will be confirmed by a SciGene representative prior to shipment.

Pricing

Prices shown are in U.S. dollars and are subject to change without notice. To receive a price quotation on special orders, contact Customer Service at 800-342-2119 or custserv@scigene.com.

Business Hours are:

8:00 AM – 4:30 PM Pacific time.

By Phone 800-342-2119
408-733-7337

By Email custserv@scigene.com

By Fax 408-733-7336

By Mail SciGene
617 N. Mary Avenue
Sunnyvale, California 94085-2907
USA

Shipments

Products are shipped FOB Sunnyvale, CA via UPS ground (or equivalent) or using the level of service specified by purchaser at time of order placement. Purchaser is responsible for all shipping charges which are prepaid and added to invoice.

Taxes

Purchaser is responsible for all state and local taxes which are prepaid and added to invoice. Tax-free institutions in California must have a tax exempt certificate on file at SciGene.

Payment

Payment is due 30 days from date of invoice on approved credit. SciGene also accepts VISA, MasterCard, AMEX and Discover cards.

CATALOG #	DESCRIPTION	UoM	PRICE
Gemini Twin Shaking Waterbaths			
RP100-0526	Replacement Bath Grill Plate for Gemini	EA	\$60.00
RP550-0085-03	Replacement Gemini Bath Assembly	EA	\$875.00
RP550-0085-04	Gemini Drain Modification Kit	EA	\$50.00
RP600-0146-04	Replacement Temperature Controller for Gemini	EA	\$350.00
RP600-0232-02	Replacement Temperature Sensor (RTD) for Gemini	EA	\$125.00
RP600-0237-01	Replacement Speed Controller for Gemini and 230V Models 400, 1000, 700 and 777	EA	\$320.00
Hybex Incubators			
RP1057-32-1	Replacement Absorbent Pad for Hybex Microarray Chamber Cover (25/pk)	PK	\$45.00
RP600-0146-04	Replacement Temperature Controller for Model 2000, Gemini and Hybex	EA	\$350.00
RP650-0670-04	Replacement O-Rings for Hybex Chamber Cover Screws (4/pk)	PK	\$2.00
RP650-0670-05	Replacement Hybex Chamber Knob (black)	EA	\$25.00
Hybridization Incubators and Microarray Ovens			
RP100-0359	Replacement Carousel Shaft for Model 400, 404, 700, and 777 Ovens	EA	\$80.00
RP100-0361-03	Replacement Idler Bearing for Model 400, 700, 777, and 2000 Ovens	EA	\$30.00
RP100-0363	Replacement Carousel Drive Coupling	EA	\$75.00
RP100-0485	Replacement Door Glass for Model 2000 Oven	EA	\$400.00
RP1040-20-1	Replacement Drip Pan for Model 2000	EA	\$100.00
RP1040-20-5	Replacement Drip Pan for Model 400	EA	\$100.00

RP550-0057-02	Replacement Solid Door Assembly for Model 400, 700 and 777 Ovens	EA	\$375.00
RP550-0059-02	Replacement Door Gasket for Model 1000	EA	\$65.00
RP600-0141	Replacement Door Hinge for Model 400, 1000, 700, and 777 Ovens	EA	\$8.00
RP600-0146-03	Replacement Temperature Controller for Model 400, 1000 and Series 700 Ovens	EA	\$350.00
RP600-0146-04	Replacement Temperature Controller for Model 2000, Gemini and Hybex	EA	\$350.00
RP600-0147	Replacement Chain Motor for Model 400, 1000 and 700 Ovens	EA	\$350.00
RP600-0148	Replacement Chain Motor for Model 777 Oven, 115V/230V	EA	\$350.00
RP600-0149-01	Replacement Door Gasket for Model 2000 Oven	FT	\$75.00
RP600-0155	Replacement Shaft Sprocket with set screws for Model 400, 700, 777 (upper)	EA	\$50.00
RP600-0156	Replacement Chain Motor Sprocket for Model 400, 1000 and Series 700 ovens (lower)	EA	\$50.00
RP600-0156-01	Replacement Sprocket (lower) for Model 777 Oven	EA	\$55.00
RP600-0157	Replacement Chain Assembly for Model 400	EA	\$50.00
RP600-0157-1	Replacement Chain Assembly for Model 310 [SPECIFY LENGTH (or # of links)]	EA	\$100.00
RP600-0157-2	Replacement Chain Assembly for Model 1000 (21.5" length)	EA	\$150.00
RP600-0212-01	Replacement Door Latch for Models 400, 700, 777, 404 and 1000 ovens	EA	\$25.00
RP600-0229-01	Replacement Tube Clip for the Model 2000 Oven Rotator	EA	\$5.00
RP600-0234-02	Replacement Drive Pulley for Model 2000 Oven. Includes 2 set screws	EA	\$40.00
RP600-0235-02	Replacement Drive Belt for Model 2000	EA	\$25.00
RP600-0237-01	Replacement Speed Controller for 115V Models 400, 1000, 700 and 777	EA	\$320.00
RP600-0264	Replacement RTD for Model 400 and Series 700 Ovens	EA	\$125.00
RP600-0267	Replacement RTD for Model 2000 Oven	EA	\$90.00
RP700-0004-03	Replacement Belt Motor for Model 2000. 115V. (w/instructions)	EA	\$225.00
RP700-0004-04	Replacement Chain Motor for Model 2000 (230V) and Model 310 (115/230V)	EA	\$300.00
RP700-0010-01	Replacement Fan Motor for Model 400	EA	\$120.00
RP700-0010-02	Replacement Fan Motor for Model 1000 and 2000 Ovens	EA	\$65.00